

# ***ABS Survey Manager***

## **SURVEY STATUS REPORT**

### **COTOPAXI**

**REGISTERED OWNER : EMPRESA PUBLICA FLOTA PETROLERA ECUATORIANA**



**Class Number : 9936457**  
**IMO Number : 9174579**  
**Print Date : Tue Sep 12 12:07:22 CDT 2017**

THIS REPORT HAS BEEN PRODUCED FROM ABS SURVEY MANAGER AND IS SUBJECT TO ERRORS AND CHANGES THAT MAY OCCUR OUTSIDE THE ABS SURVEY MANAGER APPLICATION. ABS ASSUMES NO RESPONSIBILITY FOR ERRORS OR ACTIONS TAKEN BASED ON THE INFORMATION HEREIN. ABS'S ENTIRE RESPONSIBILITY AND LIABILITY IS GOVERNED BY THE LICENSE AGREEMENT FOR ABS SURVEY MANAGER.

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

### Table of Contents

<b>Owner/Manager Address .....</b>	<b>3</b>
<b>General Characteristics .....</b>	<b>3</b>
<b>Hull .....</b>	<b>5</b>
<b>Machinery .....</b>	<b>5</b>
<b>Capacity .....</b>	<b>6</b>
<b>Lifting Equipment.....</b>	<b>6</b>
<b>Certificates .....</b>	<b>7</b>
<b>Surveys - Scheduled .....</b>	<b>9</b>
<b>Attendance - In Progress .....</b>	<b>9</b>
<b>Surveys - Incomplete .....</b>	<b>9</b>
<b>Surveys - History .....</b>	<b>10</b>
<b>Surveys - Future .....</b>	<b>12</b>
<b>Survey Parts .....</b>	<b>12</b>
<b>Class Recommendations - Open .....</b>	<b>26</b>
<b>Class Recommendations - In Progress .....</b>	<b>26</b>
<b>Statutory Deficiencies - Open .....</b>	<b>26</b>
<b>Statutory Deficiencies - In Progress .....</b>	<b>26</b>
<b>Special Findings - Open .....</b>	<b>26</b>
<b>Special Findings - In Progress .....</b>	<b>26</b>
<b>Attendance History - Last 12 months .....</b>	<b>26</b>
<b>Request For Attendance .....</b>	<b>28</b>

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

### Owner/Manager Address

#### Owning Company

**EMPRESA PUBLICA FLOTA PE  
TROLERA ECUATORIANA**

Customer Number : 215526  
Attention : ACCOUNTS PAYABLE,  
Address :

RUC: 1768164300001  
AV. DEL PACIFICO 001 Y  
PUERTO RICO  
EDIFICIO EP FLOPEC, MA  
LECON LAS PALMAS  
ESMERALDAS, Ecuador.

#### Registered Owning Company

**EMPRESA PUBLICA FLOTA PE  
TROLERA ECUATORIANA**

Customer Number : 215526  
Attention : ACCOUNTS PAYABLE,  
Address :

RUC: 1768164300001  
AV. DEL PACIFICO 001 Y  
PUERTO RICO  
EDIFICIO EP FLOPEC, MA  
LECON LAS PALMAS  
ESMERALDAS, Ecuador.

#### Account Manager

**EMPRESA PUBLICA FLOTA PETR  
OLERA ECUATORIANA**

Name (first,last): Edgar Jarrin  
Phone : 593987518636  
E-mail : vetting@flopec.com.ec  
WCN : 215526

Address :

RUC: 1768164300001  
AV. DEL PACIFICO 001 Y  
PUERTO RICO  
EDIFICIO EP FLOPEC, MA  
LECON LAS PALMAS  
ESMERALDAS, Ecuador.

#### Billing Customer

**EMPRESA PUBLICA FLOTA PE  
TROLERA ECUATORIANA**

Customer Number : 215526  
Attention : ACCOUNTS PAYABLE,  
Address :

RUC: 1768164300001  
AV. DEL PACIFICO 001 Y  
PUERTO RICO  
EDIFICIO EP FLOPEC, MA  
LECON LAS PALMAS  
ESMERALDAS, Ecuador.

#### Correspondence Customer

**EMPRESA PUBLICA FLOTA PE  
TROLERA ECUATORIANA**

Customer Number : 215526  
Attention : ACCOUNTS PAYABLE,  
Address :

RUC: 1768164300001  
AV. DEL PACIFICO 001 Y  
PUERTO RICO  
EDIFICIO EP FLOPEC, MA  
LECON LAS PALMAS  
ESMERALDAS, Ecuador.

### General Characteristics

#### Designation

Official Registry Number : TI-00-00004  
Call Sign : HCCO  
Flag Name : Ecuador  
Port of Registration : Guayaquil  
Date Of Registry :

Keel Laying Date : 16 Sep 1998  
Delivery Date : 23 Feb 1999

#### Categories

Description : Double Hull Oil Carrier  
SOLAS CATEGORY : Oil Tanker  
MARPOL CATEGORY : Crude Oil Tanker  
IBC IGC CATEGORY : Not Applicable  
ISM CATEGORY : Oil Tanker

#### ABS Class Notations

⚡ A1, Oil Carrier, ESP, Ⓢ , ⚡ AMS, ⚡ ACC, SH

#### ABS Notations

RRDA, CRC, VEC

#### Service Limit

Unrestricted Service

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

### ABS Safety, Quality and/or Environmental Standards:

International code for the security of the ships and of port facilities (ISPS Code), ABS Security Notation:

#### Anchor Equipment

Equipment Numeral : U-41  
 Anchor Holding Ability : Superior (RW)  
 Design Nominal Chain Diameter : 78 mm  
 Strength Level : Extra-high Strength

#### Other Info

Rapid Response Program : Yes

#### Principal Characteristics

Estimated Gross Tonnage : 36817.89 tonnes  
 Design Deadweight : 66160 tonnes  
 Length between perpendicular : 219 m  
 Molded Breadth(M) : 32.2  
 Molded Depth(M) : 17.85  
 Bulb Length From FP : 4.5 m  
 Web Frame Depth : 1.1 m

#### Tonnage

Regulation	Gross Tonnage	Net Tonnage
ITC	35770 (Registered)	20199 (Registered)
PANAMA		29616
SUEZ	36817.89	32497.05

#### Loading Application and Manual/Reference

Loading Manual : Yes  
 Loading Instrument : Yes  
 Trim and Stability Booklet : Yes

#### Builder

Builder	Customer Number	Builder Building ID	Builder Role	Project Description	Contractual Responsibility	Contract Date
HYUNDAI HEAVY IND. CO., LTD.	285412	1128	Prime Build			11 Jun 1998

#### Functions

Oil (F.P. 60oC or less)

#### IACS Unified Requirements Information

No IACS Unified Requirements found for this vessel.

#### IMO Requirements Information

No IMO Requirements found for this vessel.

#### Freeboard Assignments

Freeboard	Displacement	Deadweight (tonnes)	Calculated Freeboard(mm)	State
Conventional Freeboard from Ring	78336	66160	4916	Available

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

### Hull

#### Material

<u>Type</u>	<u>Primary</u>	<u>Location</u>
Ordinary Strength Steel	Yes	

#### Stiffener Systems

On Side Shell : Longitudinal

#### Bulkhead

<u>Type</u>	<u>Number</u>
Non Tight	2
Oil Tight	10

#### Tank

<u>Type</u>	<u>Number</u>
Cargo Oil	12
Ballast	10
Fuel Oil	7
Lubricating Oil	5
Fresh Water	3
Diesel Oil	3
Waste Water	2
Slop	2
Chain	1
Sludge	1

### Machinery

#### Propulsion System

##### MAIN ENGINE

Manufacturer Name :	HHI ENGINE & MACHINERY DIV.	Model Number :	5S60MC
Cylinder Bore:	600 mm	Maximum Continuous Rating:	9116.12 kW
Number of Cylinders:	5	Piston Stroke:	2292 mm

##### PROPELLER

Propeller Design Speed: 14.5 knots	Propeller Material (ABS Grade):	Bronze
------------------------------------	---------------------------------	--------

##### Tail Shaft

**Propeller Shaft Bearing**  
Bearing Lubricant: Oil

#### Steam Piping System

##### Auxiliary Water Tube Boiler P

Manufacturer Name : Aalborg Sunrod AB

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

Maximum Allowable Working Pressure: 18 bar

### Auxiliary Water Tube Boiler S

Manufacturer Name : Aalborg Sunrod AB  
Maximum Allowable Working Pressure: 18 bar

### Waste Heat Boiler<sup>1</sup>

Manufacturer Name : Kangrim Industries  
Maximum Allowable Working Pressure: 22 bar

### Main Power Distribution System

#### Aux Generator No 01 PORT<sup>1</sup>

Rated Power: 600 kW

#### Aux Generator No 02 CENTER<sup>1</sup>

Rated Power: 600 kW

#### Aux Generator No 03 STBD<sup>1</sup>

Rated Power: 600 kW

### Capacity

Compartment Capacity	Volume 100% Full(CuM)	Weight 100% Full(tonnes)
Cargo Oil Capacity	72213	67880.22
Freshwater Capacity	299	293.02
Fuel Oil Capacity	1973	1854.62
Tank Ballast Capacity	26791	26791

### Lifting Equipment

#### Crane<sup>1</sup>

Safe Working Load : 15 tonnes

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Certificate Type	Term	Flag	Issue Date	Expiry Date	Extended Date	State Date	Status
<b>Classification</b>							
Class Certificate	Full Term		16 Mar 2014	28 Feb 2019		17 May 2017	Annual Endorsement
Narrative Report - Statement of Fact	Full Term		17 Jun 2009			17 Jun 2009	Issued
Narrative Report - Statement of Fact	Full Term		02 May 2014			02 May 2014	Issued
Narrative Report - Statement of Fact	Full Term		28 Oct 2016			28 Oct 2016	Issued
Narrative Report - Statement of Fact	Full Term		28 Oct 2016			28 Oct 2016	Issued
Narrative Report - Statement of Fact	Full Term		28 Oct 2016			28 Oct 2016	Issued
<b>Marpol</b>							
Statement of Voluntary Compliance of Air Pollution Prevention (Annex VI - HSSC)	Full Term	Ecuador	12 Nov 2016	28 Feb 2019		12 Nov 2016	Issued
Statement of Voluntary Compliance for Energy Efficiency (Annex VI - HSSC)	Full Term	Ecuador	16 Mar 2014			16 Mar 2014	Issued
Statement of Voluntary Compliance for Energy Efficiency Supplement (Annex VI - HSSC)	Full Term	Ecuador	16 Mar 2014			16 Mar 2014	Issued
Statement of Voluntary Compliance of Air Pollution Prevention (Annex VI - HSSC) - Supplement	Full Term	Ecuador	12 Nov 2016			12 Nov 2016	Issued
<b>Cargo Gear</b>							
Register of Lifting Appliances			12 Apr 2015			12 Apr 2015	Annual Endorsement
Cargo Gear Certificate - Annual			17 May 2017			17 May 2017	Issued
Cargo Gear Certificate - Retesting			16 Mar 2014	16 Mar 2019		16 Mar 2014	Issued
<b>Others</b>							
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

Certificate Type	Term	Flag	Issue Date	Expiry Date	Extended Date	State Date	Status
Narrative Report - Statement of Fact	Full Term	Ecuador	27 Jun 2011			27 Jun 2011	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	16 Mar 2014			16 Mar 2014	Issued
Narrative Report - Statement of Fact	Full Term	Ecuador	16 Mar 2014			16 Mar 2014	Issued
Record of Anti-Fouling Systems	Full Term	Ecuador	28 Oct 2016			28 Oct 2016	Issued
Statement of Voluntary Compliance of Anti-Fouling System	Full Term	Ecuador	28 Oct 2016			28 Oct 2016	Issued

















## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

### Surveys - Scheduled

 indicates survey requested or in progress.

Survey Name	Status	Last Visit Date	Due Date	Range Date	Extended Date
<b>Classification</b>					
Annual Automation Survey 4			28 Feb 2018	28 Nov 2017 - 28 May 2018	
Annual Hull Survey 4			28 Feb 2018	28 Nov 2017 - 28 May 2018	
Annual Machinery Survey 4			28 Feb 2018	28 Nov 2017 - 28 May 2018	
Boiler Survey - Auxiliary Water Tube Boiler P			28 Feb 2019		
Boiler Survey - Auxiliary Water Tube Boiler S			28 Feb 2019		
Boiler Survey - Waste Heat Boiler			28 Feb 2019		
Drydocking Survey			28 Feb 2019		
Special Continuous Survey - Machinery 4		Commenced 17 May 2017	28 Feb 2019	28 Nov 2018 - 28 Feb 2019	
Special Periodical Survey - Automation 4			28 Feb 2019	28 Nov 2017 - 28 Feb 2019	
Special Periodical Survey - Hull 4			28 Feb 2019	28 Nov 2017 - 28 Feb 2019	
Tailshaft Survey - Tail Shaft - Oil			27 Oct 2021		
<b>Statutory</b>					
Annual IAPP Annex VI Survey 4			28 Feb 2018	28 Nov 2017 - 28 May 2018	
Renewal IAPP Annex VI Survey 3			28 Feb 2019	28 Nov 2018 - 28 Feb 2019	
<b>Miscellaneous</b>					
Cargo Gear Survey		17 May 2017	16 Mar 2018		

### Attendance - In Progress

No records exist for the criteria.

### Surveys - Incomplete

## ABS Survey Manager Survey Status

Name : **COTOPAXI**  
 Status : **In Operation, Active, Classed**

Class Number : **9936457**  
 IMO Number : **9174579**

Survey Name	Due Date	Status	Report Number	Report Date	Location
-------------	----------	--------	---------------	-------------	----------

Special Continuous Survey - Machinery 4	28 Feb 2019	Commenced	GY3330638-D	17 May 2017	Guayaquil
---	-------------	-----------	-------------	-------------	-----------

To complete Special Continuous Survey - Machinery 4 the following checklist items remains to be dealt with, checklist item sequence numbers 1, 2, 3, 4, 5, 6, 7, 9, 12, 13, 14, 16, 17, 18, 19, 30, 31, 33, 34, 35, 36, 37, 38, 49, 50, 71, 72, 73, 74, 75, 84

### Surveys - History For Last 5 Years

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
<b>Classification</b>					
Annual Automation Survey 3	Completed		17 May 2017	Guayaquil	GY3330638-E
Annual Hull Survey 3	Completed		17 May 2017	Guayaquil	GY3330638-C
Annual Machinery Survey 3	Completed		17 May 2017	Guayaquil	GY3330638-B
Special Continuous Survey - Machinery 4	Commenced	17 May 2017		Guayaquil	GY3330638-D
Special Continuous Survey - Machinery 4	Commenced	08 Apr 2017		Guayaquil	GY3311955-A
Intermediate Hull Survey 4	Completed		02 Dec 2016	Guayaquil	GY3248342-B
Intermediate Hull Survey 4	Commenced	12 Nov 2016		Guayaquil	GY3235956.R1-A
Boiler Survey - Auxiliary Water Tube Boiler P	Completed		28 Oct 2016	Balboa	BL3212205-C
Boiler Survey - Auxiliary Water Tube Boiler S	Completed		28 Oct 2016	Balboa	BL3212205-D
Boiler Survey - Waste Heat Boiler	Completed		28 Oct 2016	Balboa	BL3212205-E
Drydocking Survey	Completed		28 Oct 2016	Balboa	BL3212205-F
Intermediate Hull Survey 4	Commenced	28 Oct 2016		Balboa	BL3212205-B
Special Continuous Survey - Machinery 4	Commenced	28 Oct 2016		Balboa	BL3212205-A
Tailshaft Survey - Tail Shaft	Completed		28 Oct 2016	Balboa	BL3212205-G
Annual Automation Survey 2	Completed		06 May 2016	Valparaiso	VP3134063-D
Annual Hull Survey 2	Completed		06 May 2016	Valparaiso	VP3134063-C
Annual Machinery Survey 2	Completed		06 May 2016	Valparaiso	VP3134063-B
Special Continuous Survey - Machinery 4	Commenced	06 May 2016		Valparaiso	VP3134063-F
Special Continuous Survey - Machinery 4	Commenced	22 Feb 2016		Guayaquil	GY3089619-A
Annual Automation Survey 1	Completed		21 Apr 2015	Balboa	BL2885141-D
Annual Hull Survey 1	Completed		21 Apr 2015	Balboa	BL2885141-B
Annual Machinery Survey 1	Completed		21 Apr 2015	Balboa	BL2885141-A
Special Continuous Survey - Machinery 4	Commenced	21 Apr 2015		Balboa	BL2885141-C
Special Continuous Survey - Machinery 4	Commenced	12 Apr 2015		Balboa	BL2878039-B
Annual Automation Survey 5	Completed		16 Mar 2014	Valparaiso	VP2549131-E
Annual Hull Survey 5	Completed		16 Mar 2014	Valparaiso	VP2549131-B

## ABS Survey Manager Survey Status

Name : **COTOPAXI**  
 Status : **In Operation, Active, Classed**

Class Number : **9936457**  
 IMO Number : **9174579**

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
Annual Machinery Survey 5	Completed		16 Mar 2014	Valparaiso	VP2549131-A
Boiler Survey - Auxiliary Water Tube Boiler P	Completed		16 Mar 2014	Valparaiso	VP2549131-K
Boiler Survey - Auxiliary Water Tube Boiler S	Completed		16 Mar 2014	Valparaiso	VP2549131-L
Boiler Survey - Waste Heat Boiler	Completed		16 Mar 2014	Valparaiso	VP2549131-M
Drydocking Survey	Completed		16 Mar 2014	Valparaiso	VP2549131-I
Special Continuous Survey - Machinery 3	Completed		16 Mar 2014	Valparaiso	VP2549131-D
Special Periodical Survey - Automation 3	Completed		16 Mar 2014	Valparaiso	VP2549131-C
Special Periodical Survey - Hull 3	Completed		16 Mar 2014	Valparaiso	VP2549131-F
Special Continuous Survey - Machinery 3	Commenced	24 Nov 2013		Balboa	BL2490275-A
Special Continuous Survey - Machinery 3	Commenced	26 Oct 2013		Guayaquil	GY2467629-A
Annual Automation Survey 4	Completed		22 Apr 2013	Guayaquil	GY2340904-D
Annual Hull Survey 4	Completed		22 Apr 2013	Guayaquil	GY2340904-B
Annual Machinery Survey 4	Completed		22 Apr 2013	Guayaquil	GY2340904-A
Special Continuous Survey - Machinery 3	Commenced	22 Apr 2013		Guayaquil	GY2340904-C
Special Continuous Survey - Machinery 3	Commenced	12 Nov 2012		Guayaquil	GY2233596-A
Special Continuous Survey - Machinery 3	Commenced	04 Apr 2012		Valparaiso	VP2130013-E
Special Continuous Survey - Machinery 3	Commenced	18 Nov 2011		Guayaquil	GY2067714_A
Special Continuous Survey - Machinery 3	Commenced	27 Jun 2011		Valparaiso	VP2001875_A
Special Continuous Survey - Machinery 3	Commenced	23 May 2011		Guayaquil	GY1989779_A
Special Continuous Survey - Machinery 3	Commenced	15 Mar 2011		Guayaquil	GY1959698_D
Special Continuous Survey - Machinery 3	Commenced	26 Oct 2010		Guayaquil	GY1900722_A
Special Continuous Survey - Machinery 3	Commenced	26 Feb 2010		Guayaquil	GY1797931_A
Special Continuous Survey - Machinery 3	Commenced	17 Dec 2009		Guayaquil	GY1768571_B
<b>Statutory</b>					
Intermediate IAPP Annex VI Survey 3	Completed		17 May 2017	Guayaquil	GY3330638-F
Annual IAPP Annex VI Survey 2	Completed		06 May 2016	Valparaiso	VP3134063-E
Annual IAPP Annex VI Survey 1	Completed		21 Apr 2015	Balboa	BL2885141-E
Renewal IAPP Annex VI Survey 2	Completed		16 Mar 2014	Valparaiso	VP2549131-G
Annual IAPP Annex VI Survey 4	Completed		22 Apr 2013	Guayaquil	GY2340904-E
<b>Miscellaneous</b>					
Cargo Gear Survey	Completed		17 May 2017	Guayaquil	GY3330638-A

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Survey Name	Status	Last Visit Date	Done Date	Location	Report Number
Cargo Gear Survey	Completed		06 May 2016	Valparaiso	VP3134063-A
Cargo Gear Survey	Completed		12 Apr 2015	Balboa	BL2878039-A
Cargo Gear Survey	Completed		16 Mar 2014	Valparaiso	VP2549131-J
Cargo Gear Survey	Completed		22 Apr 2013	Guayaquil	GY2340904-F
Cargo Gear Survey	Completed		23 Apr 2012	Guayaquil	GY2137364-A
Cargo Gear Survey	Completed		15 Mar 2011	Guayaquil	GY1959698_A
Cargo Gear Survey	Completed		17 Dec 2009	Guayaquil	GY1768571_A
Cargo Gear Survey	Completed		05 Dec 2008	Valparaiso	VP1087894_M
Cargo Gear Survey	Completed		14 Feb 2008	Valparaiso	VP953145.R1_A
Cargo Gear Survey	Completed		27 Dec 2006	Guayaquil	GY783374_A
Cargo Gear Survey	Completed		09 Jan 2006	Guayaquil	GY670865_A
Cargo Gear Survey	Completed		19 Nov 2004	Guayaquil	GY564589_A
Cargo Gear Survey	Completed		05 Nov 2003	Valparaiso	VP470579_O
Cargo Gear Survey	Completed		13 Jun 2003	Guayaquil	GY360302_A
Cargo Gear Survey	Commenced	03 Jun 2002		Guayaquil	GY-02041_A

### Surveys - Future

Survey Name	Interval	Due Date	Left Range Date	Right Range Date	Extended Date
<b>Classification</b>					
Annual Automation Survey 4	12	28 Feb 2018	28 Nov 2017	28 May 2018	
Annual Automation Survey 5	12	28 Feb 2019	28 Nov 2018	28 Feb 2019	
Annual Hull Survey 4	12	28 Feb 2018	28 Nov 2017	28 May 2018	
Annual Hull Survey 5	12	28 Feb 2019	28 Nov 2018	28 Feb 2019	
Annual Machinery Survey 4	12	28 Feb 2018	28 Nov 2017	28 May 2018	
Annual Machinery Survey 5	12	28 Feb 2019	28 Nov 2018	28 Feb 2019	
Boiler Survey - Auxiliary Water Tube Boiler P		28 Feb 2019			
Boiler Survey - Auxiliary Water Tube Boiler S		28 Feb 2019			
Boiler Survey - Waste Heat Boiler		28 Feb 2019			
Drydocking Survey	36	28 Feb 2019			
Special Periodical Survey - Automation 4	60	28 Feb 2019	28 Nov 2017	28 Feb 2019	
Special Periodical Survey - Hull 4	60	28 Feb 2019	28 Nov 2017	28 Feb 2019	
Tailshaft Survey - Tail Shaft	60	27 Oct 2021			
<b>Statutory</b>					
Annual IAPP Annex VI Survey 4	12	28 Feb 2018	28 Nov 2017	28 May 2018	
Renewal IAPP Annex VI Survey 3	60	28 Feb 2019	28 Nov 2018	28 Feb 2019	

### Survey Parts

#### Survey Parts : Special Continuous Survey - Machinery 4

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Outfitting Item(s)	Inspection Type	Status	Due Date	Extended Date	Next Due Date
--------------------	-----------------	--------	----------	---------------	---------------

**Fire Fighting Appliances**

Breathing Apparatus (Count: 1)	Examination		05 Feb 2018		
Fire Extinguishers (Count: 1)	Examination		05 Feb 2018		
Fireman's Outfit (Count: 1)	Examination		05 Feb 2018		
International Shore Connection (Count: 1)	Examination		05 Feb 2018		

**Log Book/Calibration Record**

Camshaft Timing Record	Examination		05 Dec 2018		
Insulation Resistance Reading of Circuit	Examination		05 Feb 2018		

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
-------------------	--------	----------	---------------	---------------	----------------------

**Ballast System**

Ballast Piping <sup>1</sup>		12 Nov 2017			
Ballast Pump No 01 Inbd	Credited			09 Jan 2021	
Ballast Pump No 02 Outbd	Credited			26 Oct 2020	
Sea Chests <sup>1</sup>		16 Mar 2019			
Sea Valves <sup>1</sup>		05 Nov 2018			

**Bilge System**

Bilge Piping <sup>1</sup>		05 Sep 2017			
Bilge Suction Valve		05 Sep 2017			
Fire,General Service & Bilge Pump #1 Inbd <sup>1</sup>	Credited			09 Jan 2021	
Fire,General Service & Bilge Pump #2 Outbd <sup>1</sup>	Credited			04 Apr 2021	

**Boiler Feed Water System**

Boiler Feed Pump No 01 Inbd		05 Sep 2017			
Boiler Feed Pump No 02 Outbd	Credited			08 Apr 2022	
Boiler Feed Water Piping <sup>1</sup>	Credited			08 Apr 2022	
Boiler Water Circulator No. 01 Outbd	Credited			19 Nov 2019	
Boiler Water Circulator No. 02 Inbd	Credited			15 Sep 2020	
Waste Heat Boiler Feed Pump No.01 Inbd	Credited			15 Sep 2020	
Waste Heat Boiler Feed Pump No.02 Outbd	Credited			08 Apr 2022	

**Boiler Fuel Oil Service Piping System**

Boiler Fuel Oil Heater #1 Upper <sup>1</sup>	Credited	28 Feb 2019		27 Jun 2021	
Boiler Fuel Oil Heater #2 Lower <sup>1</sup>	Credited			27 Jun 2021	
Boiler Fuel Oil Service Pump No 01 Fwd	Credited			09 Jan 2021	
Boiler Fuel Oil Service Pump No 02 Aft	Credited			09 Jan 2021	
Boiler Lsmgo Cooler <sup>1</sup>		28 Feb 2019			
Boiler Lsmgo Cooler - Press. Test <sup>1</sup>		28 Feb 2019			
Boiler Lsmgo Pump No. 01 Stbd		28 Feb 2019			
Boiler Lsmgo Pump No. 02 Port		28 Feb 2019			
Boiler Fuel Oil Service Piping <sup>1</sup>	Credited			15 Mar 2021	

**Cargo Oil Stripping System**

Cargo Oil Stripping Piping <sup>1</sup>		12 Nov 2017			
---	--	-------------	--	--	--

## ABS Survey Manager Survey Status

Name : **COTOPAXI**  
 Status : **In Operation, Active, Classed**

Class Number : **9936457**  
 IMO Number : **9174579**

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Cargo Stripping Pump	Credited			27 Jun 2021	
<b>Compressed Air System</b>					
Compressed Air Piping <sup>1</sup>	Credited			10 May 2022	
Emergency Compressed Air Tank <sup>1</sup>		05 Sep 2017			
Emergency Compressed Air Tank Relief Vavles Qkclsvalv		05 Sep 2017			
<b>Condensate System</b>					
Air Ejector Condenser&	Credited			15 Sep 2020	
Atmospheric Condenser	Credited			15 Sep 2020	
Aux Condensate Pump No 01 #1s Copt		05 Sep 2017			
Aux Condensate Pump No 02 #2p Copt	Credited			27 Dec 2021	
Aux Condenser Vacuum	Credited			15 Sep 2020	
Condensate Piping <sup>1</sup>		05 Dec 2018			
Ejector Pump Fw Genrtr No. 1 Fwd	Credited			26 Oct 2020	
Ejector Pump Fw Genrtr No. 2 Aft		05 Dec 2018			
<b>Cooling System</b>					
Fresh Water Cooler No.01 Outbd <sup>1</sup>	Credited			15 Sep 2020	
Fresh Water Cooler No.02 Inbd <sup>1</sup>	Credited			09 Jan 2021	
Fresh Water Cooling Pump Port Use	Credited			15 Sep 2020	
Jacket Cooling Pump No.01 Fwd M/E	Credited			04 Apr 2021	
Jacket Cooling Pump No.02 Aft M/E	Credited			27 Jun 2021	
<b>Crude Oil Washing System</b>		05 Dec 2018			
Cow Piping - On Deck <sup>1</sup>		16 Mar 2019			
<b>Emergency Power Distribution System</b>					
Emergency Generator Engine With Attachments		05 Dec 2018			
<b>Emergency Shutdown System</b>					
Cargo Oil Pump Emergency Trip		12 Nov 2017			
<b>Fire Main System</b>		05 Dec 2018			
Fire Emergency Pump <sup>1</sup>	Credited			27 Dec 2021	
Fire Main Piping <sup>1</sup>		05 Sep 2017			
<b>Fresh Water Cooling System</b>					
Main Fresh Water Circulating Pump No 01 Ob Centr	Credited			04 Apr 2021	
Main Fresh Water Circulating Pump No 02 Ib Centr	Credited			10 May 2022	
<b>Fresh Water System</b>					
Evaporator No 01 Ob Fwgen	Credited			15 Sep 2020	
Evaporator No 02 Ib Fwgen	Credited			15 Sep 2020	
Fresh Water Piping <sup>1</sup>		05 Dec 2018			
<b>Fuel Oil Service System</b>		05 Nov 2018			
Fuel Oil Booster Pump No.01 Fwd G/E		10 Sep 2018			
Fuel Oil Booster Pump No.02 Aft G/E	Credited			15 Sep 2020	
Fuel Oil Circulating Pump No 01 Fwd M/E	Credited			23 May 2021	
Fuel Oil Circulating Pump No 02 Aft M/E	Credited			29 Oct 2021	
Fuel Oil Service Piping <sup>1</sup>		05 Dec 2018			
Fuel Oil Supply Pump No 01 Fwd G/E		05 Dec 2018			
Fuel Oil Supply Pump No 01 Fwd M/E		10 Sep 2018			
Fuel Oil Supply Pump No 02 Aft G/E	Credited			09 Jan 2021	

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Fuel Oil Supply Pump No 02 Aft M/E		13 Jun 2018			
<b>Fuel Oil Storage And Transfer System</b>					
Diesel Oil Pump G/E Flush		10 Sep 2018			
Diesel Oil Transfer Pump		10 Sep 2018			
Fuel Oil Heater #1lwr G/E <sup>1</sup>	Credited			27 Jun 2021	
Fuel Oil Heater #1lwr M/E <sup>1</sup>	Credited			27 Jun 2021	
Fuel Oil Heater #2upr G/E <sup>1</sup>	Credited			27 Jun 2021	
Fuel Oil Heater #2upr M/E <sup>1</sup>	Credited			27 Jun 2021	
Fuel Oil Purifier Pump Ib Supply		10 Sep 2018			
Fuel Oil Purifier Pump Ob Supply		13 Jun 2018			
Fuel Oil Storage And Transfer Piping <sup>1</sup>		05 Dec 2018			
Heater For Fuel Oil Purifier #1 Lower <sup>1</sup>	Credited			15 Sep 2020	
Heater For Fuel Oil Purifier #2 Upper <sup>1</sup>		03 Jul 2018			
Heater Tankclean		05 Dec 2018			
Heavy Oil Transfer Pump	Credited			15 Sep 2020	
Purifier No 01 For Fuel Oil	Credited			19 Nov 2019	
Purifier No 02 For Fuel Oil	Credited			19 Nov 2019	
<b>Generic System</b>					
Pump Igsdkseal No.1		11 Jan 2018			
Pump Ipsdkseal No.2	Credited			27 Dec 2021	
Pump Oilybilge	Credited			04 Apr 2021	
Pump Sludge		05 Sep 2017			
Pump Wtrscrubr		10 Sep 2018			
<b>Inert Gas System</b>		05 Dec 2018			
<b>Inert Gas System - Ops. Test <sup>1</sup></b>		05 Dec 2018			
Automatic Control Valves		26 Oct 2018			
Deck Water Seal	Credited			27 Dec 2021	
Expansion Joints		16 Mar 2019			
Fan Drives		05 Dec 2018			
Fan Drives - Megger Reading		05 Dec 2018			
Fans		26 Oct 2018			
Inert Gas Piping <sup>1</sup>		16 Mar 2019			
Non-Return Valves	Credited			04 Apr 2022	
P/V Breaker - Ops. Test <sup>1</sup>		16 Mar 2019			
P/V Breaker		16 Mar 2019			
S.W.Circulating Pump		26 Oct 2018			
Scrubber	Credited			04 Apr 2022	
<b>Lubricating Oil Service System</b>					
Camshaft Lube Oil Pump #1 Outbd	Credited			15 Sep 2020	
Camshaft Lube Oil Pump #2 Inbd	Credited			27 Jun 2021	
Lube Oil Pump #1s Main	Credited			29 Oct 2021	
Lube Oil Pump #2p Main		05 Nov 2018			
Lubricating Oil Service Piping <sup>1</sup>	Credited			08 Apr 2022	
Main Lube Oil Cooler <sup>1</sup>	Credited			28 Oct 2021	
<b>Lubricating Oil Storage And Transfer System</b>					
Heater For Lube Oil Purifier G/E <sup>1</sup>		03 Jul 2018			
Heater For Lube Oil Purifier No.1 M/E <sup>1</sup>	Credited			28 Oct 2021	
Heater For Lube Oil Purifier No.2 M/E <sup>1</sup>	Credited			29 Oct 2021	



## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Lube Oil Purifier Pump Ge Supply		10 Sep 2018			
Lube Oil Purifier Pump Me Supply	Credited			27 Jun 2021	
Lube Oil Transfer Pump	Credited			22 Feb 2021	
Lubricating Oil Storage And Transfer Piping 1		10 Sep 2018			
Purifier No 01 For Lube Oil M/E	Credited			19 Nov 2019	
Purifier No 02 For Lube Oil G/E	Credited			15 Mar 2021	
<b>Main Power Distribution System</b>					
Aux Generator Diesel No 01 With Attachments Port	Credited			26 Feb 2020	
Aux Generator Diesel No 02 With Attachments Center	Credited			26 Oct 2020	
Aux Generator Diesel No 03 With Attachments Stbd	Credited			28 Oct 2021	
Aux Switchboard		05 Nov 2018			
Electric Cables		05 Nov 2018			
Electric Fixtures		05 Nov 2018			
Electric Motors		05 Sep 2017			
Electric Motors - Megger Reading		05 Sep 2017			
Generator Trip No 01 - Reverse Power Protection	Credited			27 Jun 2021	
Generator Trip No 01 - Undervoltage Protection	Credited			27 Jun 2021	
Generator Trip No 02 - Reverse Power Protection	Credited			27 Jun 2021	
Generator Trip No 02 - Undervoltage Protection	Credited			27 Jun 2021	
Generator Trip No 03 - Reverse Power Protection	Credited			27 Jun 2021	
Generator Trip No 03 - Undervoltage Protection	Credited			27 Jun 2021	
Main Switchboard		05 Nov 2018			
<b>Main Propulsion System</b>					
Camshaft - Timing Record	Credited			22 Feb 2021	
Crankcase Relief Valves	Credited			15 Mar 2021	
Crankshaft - Deflection	Credited			15 Sep 2020	
Exhaust Manifold	Credited			27 Jun 2021	
Foundation Bolts		10 Sep 2018			
Foundation Chocks		10 Sep 2018			
Line Shaft Bearings	Credited			27 Jun 2021	
Line Shafting	Credited			27 Jun 2021	
<b>Main Engine</b>					
Cylinder Unit #1					
Crank Pin #1 <sup>1</sup>		05 Sep 2017			
Crosshead #1		05 Nov 2018			
Cylinder #1	Credited			06 May 2021	
Cylinder Head #1	Credited			06 May 2021	
Cylinder Liner #1	Credited			06 May 2021	
Cylinder Relief Valve #1 <sup>1</sup>	Credited			26 Oct 2020	



## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Exhaust Valve #1	Credited			15 Sep 2020	
Fuel Injection Pump #1	Credited			27 Dec 2021	
Fuel Injection Valve #1	Credited			27 Dec 2021	
Piston #1	Credited			06 May 2021	
Cylinder Unit #2					
Crank Pin #2 <sup>1</sup>	Credited			29 Oct 2021	
Crosshead #2	Credited			29 Oct 2021	
Cylinder #2	Credited			04 Apr 2021	
Cylinder Head #2	Credited			04 Apr 2021	
Cylinder Liner #2	Credited			04 Apr 2021	
Cylinder Relief Valve #2 <sup>1</sup>	Credited			04 Apr 2021	
Exhaust Valve #2	Credited			15 Sep 2020	
Fuel Injection Pump #2		27 Oct 2017			
Fuel Injection Valve #2	Credited			26 Oct 2020	
Piston #2	Credited			04 Apr 2021	
Cylinder Unit #3					
Crank Pin #3 <sup>1</sup>		05 Nov 2018			
Crosshead #3		05 Nov 2018			
Cylinder #3	Credited			26 Feb 2020	
Cylinder Head #3	Credited			26 Feb 2020	
Cylinder Liner #3	Credited			26 Feb 2020	
Cylinder Relief Valve #3 <sup>1</sup>	Credited			26 Feb 2020	
Exhaust Valve #3	Credited			26 Feb 2020	
Fuel Injection Pump #3		03 Jul 2018			
Fuel Injection Valve #3		03 Jul 2018			
Piston #3	Credited			26 Feb 2020	
Cylinder Unit #4					
Crank Pin #4 <sup>1</sup>		05 Nov 2018			
Crosshead #4		05 Nov 2018			
Cylinder #4	Credited			26 Oct 2020	
Cylinder Head #4	Credited			26 Oct 2020	
Cylinder Liner #4	Credited			26 Oct 2020	
Cylinder Relief Valve #4 <sup>1</sup>	Credited			26 Oct 2020	
Exhaust Valve #4	Credited			19 Nov 2019	
Fuel Injection Pump #4		26 Oct 2018			
Fuel Injection Valve #4		26 Oct 2018			
Piston #4	Credited			26 Oct 2020	
Cylinder Unit #5					
Crank Pin #5 <sup>1</sup>		05 Nov 2018			
Crosshead #5		05 Nov 2018			
Cylinder #5	Credited			19 Nov 2019	
Cylinder Head #5	Credited			19 Nov 2019	
Cylinder Liner #5	Credited			19 Nov 2019	
Cylinder Relief Valve #5 <sup>1</sup>	Credited			19 Nov 2019	
Exhaust Valve #5	Credited			15 Sep 2020	
Fuel Injection Pump #5	Credited			19 Nov 2019	
Fuel Injection Valve #5	Credited			19 Nov 2019	
Piston #5	Credited			19 Nov 2019	
Main Bearing #01		10 Sep 2018			

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Machinery Item(s)	Status	Due Date	Extended Date	Next Due Date	ABS Approved Program
Main Bearing #02	Credited			29 Oct 2021	
Main Bearing #03		10 Sep 2018			
Main Bearing #04		10 Sep 2018			
Main Bearing #05		10 Sep 2018			
Main Bearing #06		26 Oct 2018			
Main Thrust Bearing		05 Dec 2018			
Main Thrust Shaft		05 Dec 2018			
Scavenger Air Blower	Credited			27 Jun 2021	
Turbocharger	Credited			06 May 2021	
<b>Mooring System</b>					
Anchor Windlass (And Auxiliaries) Port <sup>1</sup>	Credited			27 Jun 2021	
Anchor Windlass (And Auxiliaries) Stbd <sup>1</sup>	Credited			27 Jun 2021	
<b>Oil Carrier Cargo Piping System</b>					
Cargo Oil Pump No 01 Outb	Credited			29 Oct 2021	
Cargo Oil Pump No 02 Inbd	Credited			29 Oct 2021	
Cargo Piping - On Deck <sup>1</sup>	Credited			28 Oct 2021	
Cargo Piping - On Deck <sup>1</sup>	Credited			18 Nov 2021	
<b>Oily Water Handling System</b>					
Bilge Separator Oily Wtr <sup>1</sup>	Credited			27 Jun 2021	
<b>Oxygen Acetylene System</b>					
		28 Feb 2019			
<b>Sea Water Cooling System</b>					
Salt Water Cooling Pump #1ob Copt		27 Oct 2017			
Salt Water Cooling Pump #2ib Copt	Credited			26 Oct 2020	
Salt Water Cooling Pump Port Use	Credited			04 Apr 2021	
Seawater Piping <sup>1</sup>	Credited			28 Oct 2021	
<b>Starting Air System</b>					
Starting Air Compressor No.1 Fwd		05 Nov 2018			
Starting Air Compressor No.2 Aft	Credited			04 Apr 2021	
Starting Air Piping <sup>1</sup>	Credited			27 Jun 2021	
Starting Air System	Credited			27 Jun 2021	
Compressed Air Piping <sup>1</sup>		05 Nov 2018			
Starting Air Tank No.1 Fwd <sup>1</sup>	Credited			28 Oct 2021	
Starting Air Tank No.2 Aft <sup>1</sup>	Credited			28 Oct 2021	
Starting Air Tank Relief Valve No.1 Fwd <sup>1</sup>		10 Sep 2018			
Starting Air Tank Relief Valve No.2 Aft <sup>1</sup>		10 Sep 2018			
Starting Air Valves		10 Sep 2018			
<b>Steam Piping System</b>					
Manuvering Controls		10 Sep 2018			
Steam Lines <sup>1</sup>		10 Sep 2018			
<b>Steering Gear System</b>					
Steering Gear Control System		05 Sep 2017			
Steering Gear Unit <sup>1</sup>		05 Sep 2017			
Steering Gear Unit - Pipes		05 Sep 2017			
Steering Gear Unit - Pumps		05 Sep 2017			
Steering Gear Unit - Relief Valve		05 Sep 2017			
<b>Stern Tube Lubricating System</b>					
Stem Tube Lubricationg Piping <sup>1</sup>		05 Dec 2018			
Stern Tube Lube Oil Cooler <sup>1</sup>	Credited			15 Sep 2020	
Stern Tube Lube Oil Pump No 01 Outbd	Credited			15 Sep 2020	
Stern Tube Lube Oil Pump No 02 Inbd	Credited			29 Oct 2021	

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

### Legend

<sup>1</sup> : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm<sup>2</sup>, 100 psi).

### Parts List Summary

Survey Cycle Years	1	2	3	4	5
Inspections Completion Ratio (%)	0	18	28	10	0
Number of Inspections Completed/ Remaining Count	0/238	43/195	109/129	133/105	133/105

ABS Approved Programs	PMP-PM	PMP-CM	RBI	RCM	None	TOTAL
Number of Items	0	0	0	0	233	233
Ratio of Items on PMP program	0/233 Or 0.0%					

Note:

1. An item can have multiple inspection due dates.
2. Please note items with tags 'RCM' and 'RBI' are NOT include in the ratio for PMP items.
3. Survey Cycle Years are yearly intervals from the associated cycle start date to 12 months from cycle start date, e.g. 'Year 1', is equivalent to cycle start date +12 months and so on till the 'Year 5'.
4. The above table is only displayed, when the service type is 'Classification' and the survey type is 'Special' and the mode is 'Continuous' and there are class items associated to the survey type.
5. The class item inspections, total count are items with inspection that are checked as class required inspection.
6. Inspection Completion Ratio - is the ratio of inspections completed per year against the total inspections assigned to the survey type/cycle.

### Survey Parts : Special Periodical Survey - Automation 4

Machinery Item(s)	Status	Due Date	Extended Date	Done Date	ABS Approved Program
<b>Automation Control System</b>		28 Feb 2019			
<b>Dock Trials</b>		28 Feb 2019			
<b>Manoeuvring Control And Monitoring System</b>					
Automation Control Actuators		28 Feb 2019			
Automation Insulation Resistance Control Actuators		28 Feb 2019			
Automation Insulation Resistance Control Motors		28 Feb 2019			

### Legend

<sup>1</sup> : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm<sup>2</sup>, 100 psi).

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

### Survey Parts : Special Periodical Survey - Hull 4

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
<b>Habitable</b>						
Accommodation Spaces	Overall Survey		28 Feb 2019			
Storage Spaces	Overall Survey		28 Feb 2019			
<b>Machinery</b>						
Machinery &/Or Boiler Room Spaces	Overall Survey		28 Feb 2019			
Main Pump Room	Overall Survey		28 Feb 2019			
<b>Space Arrangement</b>						
Main Hull	Thk. Meas		28 Feb 2019			
Plating In Way Of Airports	Overall Survey		28 Feb 2019			
<b>Tank - Ballast</b>						
Aft Peak Tank C	Closeup Survey		28 Feb 2019			Good
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 01 P	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 01 S	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 02 P	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 02 S	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 03 P	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 03 S	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Ballast Tank 04 P	Closeup Survey		28 Feb 2019			Fair

## ABS Survey Manager Survey Status

Name : **COTOPAXI**  
 Status : **In Operation, Active, Classed**

Class Number : **9936457**  
 IMO Number : **9174579**

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Ballast Tank 04 S	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			Fair
	Overall Survey		28 Feb 2019			
Fore Peak Tank C	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			Good
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 01 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 01 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 02 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 02 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 03 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 03 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 04 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 04 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 05 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Cargo Oil Tank 05 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 06 P	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Cargo Oil Tank 06 S	Press. Test		28 Feb 2019			
	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
<b>Tank - Diesel Oil</b>						
	Diesel Oil Service Tank P	Overall Survey	28 Feb 2019			
		Piping Exam/Test	28 Feb 2019			
Double Bottom Diesel Oil Tank P	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Double Bottom Diesel Oil Tank S	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
<b>Tank - Fresh Water</b>						
	Fresh Water Tank P	Overall Survey	28 Feb 2019			Good
		Piping Exam/Test	28 Feb 2019			
Fresh Water Tank S	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			Good
	Piping Exam/Test		28 Feb 2019			
Stern Tube Cooling Water Tank C	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
<b>Tank - Fuel Oil</b>						
	Heavy Fuel Oil Bunker Tank 01 P	Overall Survey	28 Feb 2019			
		Piping Exam/Test	28 Feb 2019			
Heavy Fuel Oil Bunker Tank 01 S	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
Heavy Fuel Oil Bunker Tank 02 P	Press. Test		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
Heavy Fuel Oil Bunker Tank 02 S	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Heavy Fuel Oil Overflow Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Heavy Fuel Oil Service Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Heavy Fuel Oil Settling Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
<b>Tank - Lubricating Oil</b>						
Cylinder Oil Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Generator Engine Lube Oil Storage Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Main Engine Lube Oil Settling Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Main Engine Lube Oil Storage Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Main Engine Lube Oil Sump Tank C	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
<b>Tank - NOT SPECIFIED</b>						
Chain Locker	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
<b>Tank - Slop</b>						
Slop Tank P	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Slop Tank S	Closeup Survey		28 Feb 2019			
	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
<b>Tank - Sludge</b>						

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Space Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date	Condition
---------------	-----------------	--------	----------	---------------	-----------	-----------

Sludge Tank P	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			

**Tank - Waste Water**

Bilge Holding Tank C	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			
Oily Bilge Tank C	Overall Survey		28 Feb 2019			
	Piping Exam/Test		28 Feb 2019			
	Press. Test		28 Feb 2019			

Structural Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date
--------------------	-----------------	--------	----------	---------------	-----------

**Structural System**

Bottom Plating	Examination		28 Feb 2019		
Deck	Examination		28 Feb 2019		
End Blkhd Of Cargo-Tank Testing (If Applicable) AFT	Examination		28 Feb 2019		
End Blkhd Of Cargo-Tank Testing (If Applicable) FWD	Examination		28 Feb 2019		
Side Shell Plating	Examination		28 Feb 2019		
Steering Gear Flat	Examination		28 Feb 2019		

Outfitting Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date
--------------------	-----------------	--------	----------	---------------	-----------

**Hull Fitting**

Hawse Pipe (Count: 1)	Examination		28 Feb 2019		
Stern Frame	Examination		28 Feb 2019		

**Vents**

Airpipe Closing Device	Examination		28 Feb 2019		
------------------------	-------------	--	-------------	--	--

Machinery Item(s)	Status	Due Date	Extended Date	Done Date	ABS Approved Program
-------------------	--------	----------	---------------	-----------	----------------------

Bilges & Drain Wells <sup>1</sup>		28 Feb 2019			
Chain Locker Pumping System		28 Feb 2019			
Bilge Piping <sup>1</sup>		28 Feb 2019			

**Mooring System**

Anchor Chains		28 Feb 2019			
Anchor(S)		28 Feb 2019			

**Sanitary Water System**

Sanitary Overboard Discharges <sup>1</sup>		28 Feb 2019			
--	--	-------------	--	--	--



## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

### **Legend**

<sup>1</sup> : Items that cannot be credited by the vessel's Chief Engineer. For heat Exchangers and Unfired Pressure Vessels this only applies if the design pressures is over 6.9 bar (7 kgf/cm<sup>2</sup>, 100 psi).

### **Cargo Gear Survey**

Item(s)	Inspection Type	Status	Due Date	Extended Date	Done Date
Crane1	Renewal. Insp. Annual. Insp.	Credited Credited	16 Mar 2018 17 May 2018		

## ABS Survey Manager Survey Status

Name : COTOPAXI  
Status : In Operation, Active, Classed

Class Number : 9936457  
IMO Number : 9174579

---

### Class Recommendations - Open

No open class recommendations have been reported as of the date of this report.

### Class Recommendations - In Progress

No in progress class recommendations have been reported as of the date of this report.

### Statutory Deficiencies - Open

No open statutory deficiencies have been reported as of the date of this report.

### Statutory Deficiencies - In Progress

No in progress statutory deficiencies have been reported as of the date of this report.

### Special Findings - Open

No open special findings have been reported as of the date of this report.

### Special Findings - In Progress

No in progress special findings have been reported as of the date of this report.

### Attendance History - Last 12 months

---

Port Office	Report Number	Last Visit Date	
Guayaquil	GY3330638	17 May 2017	
	<b>Report Number</b>	<b>Survey</b>	<b>Status</b>
	GY3330638-E	Annual Automation Survey 3	Completed
	GY3330638-C	Annual Hull Survey 3	Completed
	GY3330638-B	Annual Machinery Survey 3	Completed
	GY3330638-A	Cargo Gear Survey	Completed
	GY3330638-F	Intermediate IAPP Annex VI Survey 3	Completed
	GY3330638-D	Special Continuous Survey - Machinery 4	Commenced
	GY3330638-G	Survey for Compliance - Statutory	Completed
Guayaquil	GY3311955	08 Apr 2017	
	<b>Report Number</b>	<b>Survey</b>	<b>Status</b>
	GY3311955-A	Special Continuous Survey - Machinery 4	Commenced
Guayaquil	GY3248342	02 Dec 2016	
	<b>Report Number</b>	<b>Survey</b>	<b>Status</b>
	GY3248342-B	Intermediate Hull Survey 4	Completed

---

## ABS Survey Manager Survey Status

Name : COTOPAXI  
 Status : In Operation, Active, Classed

Class Number : 9936457  
 IMO Number : 9174579

Port Office	Report Number	Last Visit Date	Status
	GY3248342-A	Survey for Compliance - Class	Completed
Guayaquil	GY3242431	24 Nov 2016	
	<b>Report Number</b> GY3242431-A	<b>Survey</b> Survey for Compliance - Class	<b>Status</b> Completed
Guayaquil	GY3235956.R1	12 Nov 2016	
	<b>Report Number</b> GY3235956.R1-A GY3235956.R1-C GY3235956.R1-D GY3235956.R1-B	<b>Survey</b> Intermediate Hull Survey 4 Other Survey (Statutory) Repair Survey (Class) Survey for Compliance - Class	<b>Status</b> Commenced Completed Completed Completed
Balboa	BL3212205	28 Oct 2016	
	<b>Report Number</b> BL3212205-C BL3212205-D BL3212205-E BL3212205-F BL3212205-B BL3212205-H BL3212205-A BL3212205-I BL3212205-G	<b>Survey</b> Boiler Survey - Auxiliary Water Tube Boiler P Boiler Survey - Auxiliary Water Tube Boiler S Boiler Survey - Waste Heat Boiler Drydocking Survey Intermediate Hull Survey 4 Repair Survey (Class) Special Continuous Survey - Machinery 4 Statement of Fact Survey Tailshaft Survey - Tail Shaft	<b>Status</b> Completed Completed Completed Completed Commenced Completed Commenced Completed Completed

**ABS Survey Manager Survey Status**

Name : **COTOPAXI**  
Status : **In Operation, Active, Classed**

Class Number : **9936457**  
IMO Number : **9174579**

**Request For Attendance**

To ABS Office At: \_\_\_\_\_ ABS Fax No: \_\_\_\_\_

**Attn: Surveyor-in-Charge**

**Requestor's Name :** \_\_\_\_\_

**Requestor's Company :** \_\_\_\_\_

**Requestor's Company Address:** \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

**Requestor's Tel. #:** \_\_\_\_\_

**Local Contact Details :** \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

**Billing Customer Name :** \_\_\_\_\_

**Billing Customer Address :** \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

Name : **COTOPAXI**

ABSID : **9936457**

Customer W.O/P.O. (if any) : \_\_\_\_\_

Date and Time of Survey : \_\_\_\_\_

Place of Survey : \_\_\_\_\_

We hereby request attendance for the attached surveys/items checked. If any surveys/items are not checked, please explain in the reason for each :

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
Requestor's Signature

**ABS Survey Manager Survey Status**

Name : **COTOPAXI**  
Status : **In Operation, Active, Classed**

Class Number : **9936457**  
IMO Number : **9174579**

---

\*Note: The survey overdue date includes the window of time allotted for completion of annual and intermediate surveys, as applicable.

---

ADDITIONAL: List any additional surveys/items that are not checked above that you wish to include at this time.

---

---

---

---